

Structural repairs –

The owner of this guitar feared it was a lost cause. The top was “soft” and structurally unable to withstand string tension. His “old friend” had become a wall decoration (unplayable). After re-hydration of the body, gluing loose braces (6), a fret dress, new bone nut and compensated saddle the guitar was returned to the owner in perfect playing condition.

