

Finish Repair:

The finish on the headstock of this beautiful Guild dreadnought had been damaged when the nut was removed. Playability was unaffected but the blemish was too irritating to ignore. The instrument had come in for an upgrade to bone nut and saddle. The customer was thrilled to have the warm sound and sustain that bone can give and cosmetic work that restored the headstock to its original state.

